



VGB COMPLIANT DEBRIS DRAIN

# CERTIFICATE OF CONFORMITY

**1. PRODUCT: MDX-R3 VGB COMPLIANT DEBRIS DRAIN**

- MDX-R3 US
- XXX-262-2240-XX CONCRETE ADJUSTABLE
- XXX-262-2243-XX CONCRETE NON ADJUSTABLE
- XXX-272-2240-XX VINYL
- XXX-282-2240-XX FIBERGLASS
- MDX-R3 AU
- XXX-262-2241-XX CONCRETE ADJUSTABLE
- XXX-262-2244-XX CONCRETE NON ADJUSTABLE
- XXX-272-2241-XX VINYL
- XXX-282-2241-XX FIBERGLASS
- MDX-R3 EU
- XXX-262-2242-XX CONCRETE ADJUSTABLE
- XXX-262-2245-XX CONCRETE NON ADJUSTABLE
- XXX-272-2242-XX VINYL
- XXX-282-2242-XX FIBERGLASS
- XX DESIGNATES COLOR

The MDX-R3 VGB Compliant Debris Drain is a 14" diameter drain fitting. It includes a sump, an enlarged suction element and a reducer adapter to 2 1/2" with a funnel shaped cover that is affixed to a concrete leveling ring or directly to the sump. The drain has a single C shaped opening to accept large debris.

**2. APPLICABLE STANDARD OR REGULATION:**

- VGB Pool and Spa Safety Act 2008
- ASME A112.19.8-2009B
- ANSI/APSP-7 2006

**3. DOMESTIC MANUFACTURER:**

- Paramount Leisure Industries
- DBA/ Paramount Pool and Spa Systems
- 295 E Corporate Plc #100
- Chandler, AZ 85225
- 480-893-7607
- 800-621-5886

**4. US IMPORTER: N/A**

**5. PRIVATE LABELER: N/A**

**6. Test Record Documentation:**

- Dominic Conn
- Director of Engineering
- Paramount Pool and Spa Systems
- Chandler, AZ 85225
- dconn@1paramount.com
- 480-893-7607x250
- Tony Zhou
- IAPMO R&T Lab
- Manager Testing
- 5001 East Philadelphia Street
- Ontario, CA 91761
- tony.zhou@iapmortl.org
- 909-472-4243

**7. Date and Place of Manufacture:**

- October 2010
- Chandler AZ

**8. Date and Location of Test Report:**

- September 28, 2010
- IAPMO R&T Lab

**9. Name of Third Party laboratory:**

- IAPMO R&T Lab
- 5001 East Philadelphia Street
- Ontario, CA 91761-2816 USA

Install Date \_\_\_\_\_

Replacement 5 years from installed date \_\_\_\_\_